

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2022

Submitted Date:

10/11/2022

Document Number:

695106855

**FIELD INSPECTION FORM**

Loc ID 322246 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**  
OGCC Operator Number: 44390  
Name of Operator: JAVERNICK OIL  
Address: 3040 E MAIN  
City: CANON CITY State: CO Zip: 81212

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
6 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301365	WELL	SI	12/01/2021	OW	043-06169	ROYAL GORGE 8	SI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED EQUIPMENT THERE IS NO PRIME MOVER FOR PUMPJACK (JUMPJACK MUST BE OPERATIONAL TO BE CONSIDERED USABLE EQUIPMENT).		
Corrective Action:	REMOVE UNUSED EQUIPMENT OR REPAIR MECHANICAL ISSUE PER RULE 606.	Date:	11/11/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Type: Bradenhead	# 1			
Comment:	IS ACCESSABLE			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		38.350126,-105.125013
Comment:	NFPA STICKER IS WEATHERED AND BRAKING APART IT WILL NEED REPLACED SOON.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	YES		
Comment:	FLIR CAMERA SHOWS STEADY GAS FROM TANK HATCH ON TOP OF CRUDE OIL TANK. NOTE: THE VALVES ON THE 2" LINE FROM THE WELLHEAD TO THE TANK ARE OPEN.		
Corrective Action:	Immediately cease venting/flaring.	Date:	10/12/2022

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 301365 Type: WELL API Number: 043-06169 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: WELL IS TA (NO PRIME MOVER ON PUMP JACK)

Corrective Action: \_\_\_\_\_

Date: 11/11/2022

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403194307	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883571">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883571</a>
695106856	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883558">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883558</a>
695106857	FLIR VIDEO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883559">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883559</a>