

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2022

Submitted Date:

10/11/2022

Document Number:

707900052

FIELD INSPECTION FORM

Loc ID 322234 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10417
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC
Address: 113 N SANTA FE AVE
City: FLORENCE State: CO Zip: 81226

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Whisler, John	720-763-3184	jwhisler@i-og.net	All Inspections
Harkins, Liz		lharkins@fremontpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295254	WELL	SI	08/01/2022	OW	043-06150	RAINBOW 23-20	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	mechanical issue Well head leaking around tubing		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	10/12/2022

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Cattle panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 4		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3		STEEL AST		38.378896,-105.137501	
Comment:		Sign not posted or information inaccurate at battery no volume sign and NFPA placards are faded				
Corrective Action:		Install sign to comply with Rule 605.d.			Date:	11/11/2022
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 295254 Type: WELL API Number: 043-06150 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection well was SI but rig on site. forms 42 and 6 on file with the COGCC.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/17/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday October 11, 2022 at approximately 9:41AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Rainbow #27-20 Operator: Incremental Oil and Gas (Freemont) API#: 043-06150 County: Fremont While there, I observed a SI well site With P&A operation to begin. During this inspection the following possible compliance issues were observed: Mechanical issue: Rule 608 e Corrective action date of 10-12-22 see video Signs: Rule 605d Corrective action date of 11-11-22 See photos. Weather conditions: Clear At approx. 9:56AN I spoke with Liz Harkin informed her of leaking well head she said she will send someone to repair. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	10/11/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403194421	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883660
707900053	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883645
707900054	Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883646