



Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #1 Area near spill origin. Note staining on pipe insulation.



Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #2 Tank that is directly across from spill origin. Tank is approximately 30 feet from spill origin. Photo taken looking south.





Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #3 area of spill origin. Note: blind flange at top of photo, this was the area where the pipe failed. Photo is taken looking north.





Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #4 Spill origin is to the right and 10 feet behind camera. Photo is taken looking west.





Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #5 close up of Storage shed on the north side of location, that parallels the perimeter road. Note: high water mark of spill on building footer, some stained soil below the swamp cooler.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #6 Building on the right contained the failed pipe. The Building on the left appeared to be used as a Storage shed it is on north side of the location, this building that parallels the perimeter road. Photo taken looking east.





Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #7 The surface water ditch captured some of the spilled fluid. It is believed, that water from ditch is directed through a culvert then to a ditch and ultimately to an emergency pit, Facility 102564.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #8 this ditch collected the spilled fluid and directed it to emergency pit. There was some salt staining observed, no hydrocarbon staining was observed in this portion of the spill path.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #9 This ditch collected the spilled fluid and directed it to emergency pit. There was some salt staining observed, no hydrocarbon staining was observed in this portion of the spill path. Note: just to the lookers left of the excavator is a fence, this is the perimeter fence to the emergency Pit. The pump truck in photo was finishing collecting fluid from a water wash of the spill path.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #10 This ditch collected the spilled fluid and directed it to emergency pit. There was some salt staining observed, no hydrocarbon staining was observed in this portion of the spill path. Note: photo is looking east-southeast, taken between pit and Main Water Plant.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #11 Emergency Pit at Main water Plant, Facility 102564





Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #12 11 Emergency Pit at Main water Plant, Facility 102564





Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo # 11 Emergency Pit at Main water Plant, Facility 102564. Note: potential gap in fence.





Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #14 11 Emergency Pit at Main water Plant, Facility 102564





Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #15 this gate is near the following lat/long that was recorded via camera; 40.099572,-108.859017. It is was told to COGCC that this gate was closed at the time of the spill, this directed water to the area behind the gate, in this photo and ultimately to the Pit. Behind this gate, was dry.



Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #16 spill path between the facility and pit. NO hydrocarbon was observable in this portion of spill. This area was water washed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection
Photos
spill # 483023
Inspection Date:
10/6/2022
All Photos taken
by Kris Neidel

Photo #17 spill path between the facility and pit. NO hydrocarbon was observable in this portion of spill. This area was water washed.



10.06.2022 13:51

Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #17 is taken on emergency access road for pit, on the northeast side of pit. It appears this side of the pit is not frequently used for maintaining the pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection

Photos

spill # 483023

Inspection Date:

10/6/2022

All Photos taken

by Kris Neidel

Photo #18 17 is taken on emergency access road for pit, on the northeast side of pit. It appears this side of the pit is not frequently used for maintaining the pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources