

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 2	automation			
Bradenhead	# 2	appear plumbed to surface			
	#	See Inspection Doc # 693502181 for related shared facilities and equipment.			
Plunger Lift	# 2				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 693502181 for related shared facilities and equipment.				
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date: <input style="width: 50px;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width: 50px;" type="text"/>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <input style="width: 50px;" type="text"/>

Inspected Facilities

Facility ID: 429490 Type: WELL API Number: 123-35810 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/15/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 120 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10-19-2022 at approximately 1050 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Civitas/Crestone Peak Resources Location name: Echeverria 2B-2H API #05-123-35810 County: Weld Weather: Clear. Location: Dry. While there, I observed a multi well pad, 1 well is PR and 1 well is SI at the time of inspection. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	10/19/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401202	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5890882