

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | | Date: |

Overall Good:

| | | | |
|----------------------|----------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | Signs legible with contact information | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|--|--|-------|
| Fencing/: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | | |
|--------------------|------|--|--|-----------------|
| Equipment: | | | | corrective date |
| Type: Other | # | | | |
| Comment: | BOPE | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|-------------------------|--------------------------------------|----------|-----------|---------|-----------------------|
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 2 | 300 BBLS | STEEL AST | | 37.002963,-106.881533 |
| Comment: | 2 above ground produced water tanks. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | |
|------------------|--|--|--|
| Condition | | | |
| Other (Content) | | | |
| Other (Capacity) | | | |

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Other (Type) _____ | | | | |
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Venting: | | | | |
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected FacilitiesFacility ID: 296473 Type: WELL API Number: 007-06256 Status: SI Insp. Status: WK**Workover**Comment: Drake Well Service workover rig on site.Corrective Action: Date: **COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>Observation of plugging and abandoning operations on 10/14/2022 and 10/15/2022.</p> <p>10/14/2022 - Retainer set @ 1194'. 12 sx cement from 1194'-1210'. Casing pressure tested @ 500 psi and held for 30 minutes. Jet West Wireline perfed @ 513' Waited on suck truck but equipment did not work so SDFN.</p> <p>10/15/2022 - Well was bled down and water was circulated to clean out hole. Drake Well Service pumped 50sx in the annulus and 36sx inside 4.5" from 513' to surface @ 14.7 wt with good returns Circulated 3 bbls to surface. Rigged down and SDFN</p> | durana | 10/17/2022 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 694600144 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891302 |