

Inspection Photos
Location Name: Marjo #M2
Location ID: 322261



Photo 1 loc pic

Photo 2 Well head

Inspection Photos
Location Name: Marjo #M2
Location ID: 322261



Photo 3 No volume or tank lable



Photo 4 Stained soil Crude oil load out line. Mechanical issue

Inspection Photos
Location Name: Marjo #M2
Location ID: 322261



Photo 5 stained soil under Pumping unit. Mechanical issue