

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2022

Submitted Date:

10/19/2022

Document Number:

707900076

FIELD INSPECTION FORM

Loc ID 322233 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments5 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291241	WELL	PR	08/01/2010	OW	043-06149	DRAPER 2	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment, 2" steel pipe and 1" poly		
Corrective Action:	Comply with rule 606	Date:	11/19/2022
Type	OTHER		
Comment:	Stained soil around well head		
Corrective Action:	Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS 905 e	Date:	11/19/2022
Type	OTHER		
Comment:	Mechanical issue leaking flow lines off well head		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	11/19/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		

Comment: Unused equipment Crude oil tank is not connected to anything

Corrective Action: Comply with rule 606	Date: <u>11/19/2022</u>
--	-------------------------

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Gas being vented or flared during non-upset condition without prior approval from COGCC.		
Corrective Action:	Immediately cease venting/flaring per rule 903 d (2)		Date: <u>10/20/2022</u>

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 291241 Type: WELL API Number: 043-06149 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/22/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday October 19, 2022 at approximately 4:28PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Draper #2 Operator: Javernick Oil API#: 043-06149 County: Freemont While there, I observed a producing well site and facility. During this inspection the following possible compliance issues were observed: Venting: Rule 903 d (2) Corrective action date of 10-20-22 See photo 8 Unused equipment: Rule 606 Corrective action date of 11-19-22 See photos 1,2,3 Mechanical issue: Rule 608e Corrective action date of 11-19-22 See photos ,5 Stained soil: Rule 905e Corrective action date of 11-19-22 Contact COGCC area EPS See photos 2,5,6 At time of inspection it appears 1/2 line off well head was in the open position and venting gas. Weather conditions: Clear A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	10/19/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900077	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891347