

Interim Reclamation Inspection

October 11, 2022

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 480698

Inspection Document #: 697504285

Weld County, CO

NWSE Section 11 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Martin J Schaefer #2 Flowline
Location ID: 480698



Photo 1. COGCC drone aerial imagery taken on October 11, 2022 documenting the scope of reclamation work that has been performed. The red polygon has been seeded and hydromulched.

Inspection Photos
Location Name: Martin J Schaefer #2 Flowline
Location ID: 480698



Photo 2. COGCC drone aerial imagery taken on October 11, 2022 documenting the scope of reclamation work that has been performed. The red polygon has been seeded and hydromulched.

Inspection Photos
Location Name: Martin J Schaefer #2 Flowline
Location ID: 480698



Photo 3. COGCC drone aerial imagery taken on October 11, 2022 documenting the scope of reclamation work that has been performed. The red polygon has been seeded and hydromulched. Note- the north-facing fill slope is going to require additional stabilization and the Operator is addressing that.

Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



Photo 4. Photo taken from the eastern access road, facing East. Photo illustrates the access road has been seeded and hydromulched. Germination of desirable plant species was observed.



Photo 5. Close up photo illustrating germination of desirable plant species.

Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



Photo 6. Photo taken from the eastern staging area, facing Northeast. See comments under Photo 4.



Photo 7. Photo taken from the eastern staging area, facing East. See comments under Photo 4.

Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



Photo 8. Photo taken from the central access road, facing West. See comments under Photo 4.



Photo 9. Photo taken from the western access road, facing East. See comments under Photo 4.

Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



Photo 10. Photo taken from the western staging area, facing West. See comments under Photo 4.



Photo 11. Photo taken from the western excavation area, facing West. See comments under Photo 4. Note- vehicle traffic appears to be driving over reclamation area. Operator will work to keep vehicle traffic off while reclamation is in progress.

Inspection Photos

Location Name: Martin J Schaefer #2 Flowline

Location ID: 480698



Photo 12. Photo taken from the western fill slope on 9/13/2022, facing North. Photo illustrates erosion along the fill slope that needs to be repaired during reclamation. The erosion is believed to be from a recent irrigation event by the surface owner.



Photo 13. Photo taken from the western fill slope on 10/11/2022, facing East. Photo illustrates erosion along the fill slope has been repaired but there appears to be movement of the slope. Operator is planning to implement additional BMPs to better stabilize the fill slope for long-term stabilization.