

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/20/2022

Submitted Date:

10/20/2022

Document Number:

702500642

FIELD INSPECTION FORM

 Loc ID 325165 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num:
Operator Information:
 OGCC Operator Number: 10766
 Name of Operator: ARKOMA OPERATIONS LLC
 Address: 2121 S COLUMBIA AVE SUITE 101
 City: TULSA State: OK Zip: 74114
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		SJBcompliance@arkomaops.com	ALL SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Price, Andrew	918-260-8324	aprice@arkomaops.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214181	WELL	PR	07/01/2022	GW	067-05501	MILLER MESAVERDE UNIT 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Pig Station	# 1				
		Comment:			
		Corrective Action:		Date:	
Type: Deadman # & Marked	# 2				
		Comment:			
		Corrective Action:		Date:	
Type: Gas Meter Run	# 1				
		Comment: Gas meter calibration is within the last year.			
		Corrective Action:		Date:	
Type: Bradenhead	# 1				
		Comment: Bradenhead is accessible.			
		Corrective Action:		Date:	
Type: Flow Line	# 2				
		Comment: 2" line from wellhead to separator, 4" line from gas meter run to off location.			
		Corrective Action:		Date:	
Type: Horizontal Separator	# 1				
		Comment:			
		Corrective Action:		Date:	
Type: Plunger Lift	# 1				
		Comment:			
		Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.128442,-107.755603
		Comment: Open topped produced water tank with steel mesh screen covering.			
		Corrective Action:		Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	40 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Berm height is diminished on northeast corner. Secondary containment is inadequate to contain 150% of the volume of the largest tank.			
Corrective Action:	Repair berms or other secondary containment devices per Rule 603.o.			Date: 11/20/2022

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214181 Type: WELL API Number: 067-05501 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500643	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5892405