

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2022

Submitted Date:

10/14/2022

Document Number:

699805061

**FIELD INSPECTION FORM**

Loc ID 322510 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210663	WELL	PR	01/01/2020	GW	045-06419	MOBILE 11-20	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Thursday 10/13/22 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC MOBILE-66S92W /20NESW. Location #322510 in Garfield County Colorado. While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 10/28/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

<b>Equipment:</b>		corrective date
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Taylor plug located on braden heads. All braden head valves are accessible.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 210663 Type: WELL API Number: 045-06419 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Sediment Traps						
		Culverts				
Compaction	Fail					Location lacks stabilization.
Ditches						
		Ditches				
Other	Fail					Insufficient tracking BMP at entrance to location
Berms						
Gravel	Fail					Gravel insufficient
		Gravel				
		Check Dams				
		Sediment Traps				

Comment: [Location lacks stabilization. Insufficient tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 10/28/2022

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to storm water for corrective actions.</a>	depaoloc	10/14/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403197945	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5886679">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5886679</a>
699805062	Photos for Insp. #699805061	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5886675">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5886675</a>