

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/13/2022

Submitted Date:

10/14/2022

Document Number:

702500604**FIELD INSPECTION FORM**Loc ID 320915 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	Owner
Duran, Alicia		alicia.duran@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296473	WELL	SI	09/01/2021	OW	007-06256	MARTINEZ 1A	WK

General Comment:

Inspector Alex Klink on site to observe Plugging and Abandoning procedures. Company man on location is Todd Moore. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

At time of inspection workover rig was arriving on location and preparing to rig up. Bradenhead test had been conducted on 10/12/22, with initial pressures of 0 PSI on bradenhead and production casing. At time of inspection a Form 17 had not been submitted.

There are an adequate amount of fire extinguishers on location, directional rig signs, and an open top tank on site. No portable toilets on location.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Oily sucker rods stacked on surface material (IMG 06). Oil has impacted surface material (IMG 07).		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. Improve materials handling.		Date: 10/14/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 1		corrective date
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		37.002963,-106.881533
Comment:	2 above ground produced water tanks, each with 300 bbl capacity.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 296473 Type: WELL API Number: 007-06256 Status: SI Insp. Status: WK**Cement**Cement ContractorContractor Name: Drake Well Service

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment:

At time of inspection workover rig was arriving on location and preparing to rig up. Bradenhead test had been conducted on 10/12/22, with initial pressures of 0 PSI on bradenhead and production casing. At time of inspection a Form 17 had not been submitted.

There are an adequate amount of fire extinguishers on location, directional rig signs, and an open top tank on site. No portable toilets on location.

No portable toilet or sanitary facility on site.

Corrective Action: **Provide self contained sanitary facility per rule 602.m**

Date: 10/15/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403197516	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5886348
702500606	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5886347