

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SENW

Location ID: 311608



Photo #8089 From entrance to location.



Photo #8090 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SENW

Location ID: 311608




Photo #8092 Chemical tank missing required information.



Photo #8093 Unused Chemical tank.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SENW

Location ID: 311608



Photo #8095 Location lacks stabilization.



Photo #8096 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SENW

Location ID: 311608



Photo #8098 Location lacks stabilization.



Photo #8099 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SENW

Location ID: 311608



Photo #8100 Insufficient tracking BMP at entrance to location.