

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2022

Submitted Date:

10/21/2022

Document Number:

699805094

FIELD INSPECTION FORMLoc ID 322456 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

General Comment:

COGCC Inspection Report Summary
On Thursday 10/20/22 at approximately 14:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH-66S94W /20SENE.
Location #322456 in Garfield County Colorado.
While there, I observed normal production operations.
During this inspection the following compliance issues were observed:

1) Sign weathered and not legible with a corrective action date of 11/20/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign weathered and not legible.		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged signs.	Date:	11/20/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Chemical tank			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Berms				
Sediment Traps						
Compaction						
		Ditches				
Berms						
		Compaction				
Gravel						
		Culverts				
		Sediment Traps				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	10/21/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805095	Photos for Insp. #699805094	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5893561