

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2022

Submitted Date:

10/23/2022

Document Number:

707600390**FIELD INSPECTION FORM**Loc ID 323559 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245400	WELL	TA	12/01/2021	OW	123-13195	WPF III A18-2	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive / Shut-down.

Centralized Battery serves 1 Location ID
(323559).

(Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery formerly served 2 Location IDs
(310589, 420580).

(Well(s): 2: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #707600384 and/or Location ID #323559
for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #707600384 dated 10/18/2022.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Prior insp: Weed encroachment at wellsite. Refer to Rule 606.c for guidance.. Remove, manage, & control weeds around wellsite. Comply with Rule 606.c. Corrective Action date: 10/27/2022.</p> <p>This insp: * Weeds around wellsite NOW appear mitigated. See photos #1, 2.</p>		
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Type	SEPARATOR				
Comment:	Surrounded by earth berms.				
Corrective Action:				Date:	
Equipment:					corrective date
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	1: Solar power bank. 2: ECD scrubber(s).				
Corrective Action:				Date:	
Type: Bird Protectors	# 4				
Comment:					
Corrective Action:				Date:	
Type: Emission Control Device	# 2				
Comment:	ECD 1: Crude oil tank vapor line combustor(s). Controls crude oil tank(s) vapors. Pilot(s): OFF. Inactive. Shut-down. ECD 2: Separator vapor line combustor(s). Controls separator vapors. Pilot(s): OFF. Inactive. Shut-down.				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Gas Sales: Calibration card indicates NO calibration within last year. Last calibration: 03/19/2019. Inactive, no production.				
Corrective Action:				Date:	
Type: Other	# 1				
Comment:	Wellhead: w/ Master & casing valves.				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Location ID (323559). (Well(s): 1: Temporarily Abandoned TA). Centralized Battery formerly served 2 Location IDs (310589, 420580). (Well(s): 2: Plugged & Abandoned PA).				
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLS	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity) 60 Bbls.						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent	Adequate	
Comment: Shares berms w/ crude oil tank(s).						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST		40.492857,-104.592665	
Comment: Equalizer line(s) connect crude oil tanks.						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent	Adequate	
Comment: Shares berms w/ produced H2O vault(s).						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 245400 Type: WELL API Number: 123-13195 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Well disconnected from flowline.
COGCC records last production: 08/2017.

Form 4 on file. TA date: 10/02/2020. Approved.
Form 21-MIT on file. Date: 10/14/2020. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 04/17/2020. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/09/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 10/21/2022 at approximately 14:41 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WPF III-66N64W/18NWNE Location ID: 323559 Well Name(s): WPF III A18-2. API: 123-13195. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed:</p> <p>Well(s): 1: Temporarily Abandoned TA. Battery: Inactive / Shut-down.</p> <p>Centralized Battery serves 1 Location ID (323559). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 2 Location IDs (310589, 420580). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #707600384 and/or Location ID #323559 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #707600384 dated 10/18/2022.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Weed encroachment at wellsite. Refer to Rule 606.c for guidance.. Remove, manage, & control weeds around wellsite. Comply with Rule 606.c. Corrective Action date: 10/27/2022. * Weeds around wellsite NOW appear mitigated. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/22/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600392	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5893973