

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2022

Submitted Date:

10/19/2022

Document Number:

688313280**FIELD INSPECTION FORM**Loc ID 302966 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 55030Name of Operator: MCCARTNEY ENGINEERING LLCAddress: 4251 KIPLING ST STE 575City: WHEAT RIDGE State: CO Zip: 80033**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McCartney, Jack	303-830-7208	jack@mccartneyengineering.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252056	WELL	SI	05/01/2022	GW	125-05105	SEEDORF 1	PA

General Comment:PA Inspection

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:	Excell sign at CR 39		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	operator has contacted midstream for removal		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:	empty				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected FacilitiesFacility ID: 252056 Type: WELL API Number: 125-05105 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: Excell

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 2790, 1400, 500Cement Volume (sx): 52

Good Return During Job: _____

Cement Type: _____

Comment: [Excell Services on location 10/18/2022 and had pulled tubing and packer on 10/17/2022. BRHD 0 psi.](#)
[LogTech Wireline on location 10/17/2020 to set bottom CIBP at 2790' \(limited by collar locations-came up 10'\), set two cement sxs on top of plug, shot 4 holes at 1400' and 500', set CIBP at 1350' and 450'.](#)
[Excell pumped ~40sxs, 15.4 ppg \(3 bpm, up to 500 psi\) cement thru 1350' CIBP leaving 10 sxs cement on top](#)
[Water from Wray](#)

[10/19/2022 DNW](#)
[Excell pumped 203 sxs cement at surface plug, 158 sxs below and 45 above](#)

Corrective Action: _____

Date: _____

Workover

Comment: [Excell Rig 8, Andy B.](#)
[No BOPs](#)
[10 bbls water to kill well](#)

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688313281	McCartney Seedorf Day 1 PA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5894448