

# Inspection Photos and Issue Report

10/17/2022

Operator: LARAMIE ENERGY LLC - 10433

Location #335889

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335889



**Photo 1:** Photo taken from the Location, facing north. Photo shows large areas where control measures to protect, stabilize, as well as to minimize erosion and degradation at the cut slopes of the Location remain missing or insufficient.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335889



**Photo 2:** Photo shows large areas where control measures to protect, stabilize, as well as to minimize erosion and degradation at the cut slopes of the Location remain missing or insufficient.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335889



**Photo 3:** Continued from photo 2. Photo shows sediment/material eroding from the slopes have covered what appears to have be straw mulch applied to the slopes. BMP observed inadequate to protect, stabilize, as well as to minimize erosion and degradation at the cut slopes; erosion degradation has persisted.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335889



**Photo 4:** Photo taken from the toe of the cut slopes. Photo shows sediment deposition due to erosion degradation at the cut slopes.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335889



**Photo 5:** Photo taken from the cut slopes. Photo shows the erosion control blankets previously implemented have not been maintained in a proper functioning condition per good engineering practices. Erosion degradation has persisted.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335889



**Photo 3:** Photo taken from the cut slopes. Photo shows the erosion control blankets previously implemented have not been maintained in a proper functioning condition per good engineering practices. Erosion degradation has persisted. Arrow shows blanket in disrepair, as well as sediment/material eroding from the slopes covering remaining erosion blankets.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location #335889



**Photo 7:** See comments under photo 6.