

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2022

Submitted Date:

10/25/2022

Document Number:

705000021**FIELD INSPECTION FORM**Loc ID 336697 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| | | COGCCInspections@Oxy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 250288 | WELL | SI | 08/01/2022 | GW | 123-18091 | PSC 43-11 | PA |
| 286038 | WELL | SI | 06/01/2022 | OW | 123-24103 | PSC 39-11 | PA |

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 250288 Type: WELL API Number: 123-18091 Status: SI Insp. Status: PA

Facility ID: 286038 Type: WELL API Number: 123-24103 Status: SI Insp. Status: PA

Flowline

| | | |
|----|---------------------|----------|
| #1 | Type: Non-Well Site | of Lines |
|----|---------------------|----------|

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Wells (PSC 43-11, 39-11) have been plugged and abandoned; cut and cap operations have been completed. COGCC form 42 notice of start of plugging operations received 07/2022. The wellhead flowlines (OLF) have been removed. COGCC form 42 notice of flowline abandonment completed received on 10/2022. The on location dump and process flowlines at facility/ battery have been removed. No flowline risers were observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment have been removed. Fenced excavations were observed at the PA wellheads; remediation work is in progress (historical). No Oxy personnel were on location at the time of inspection.

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| As outlined on COGCC form 19 spill report Doc #403200078 received on 10/20/2022: On October 17, 2022, soil impacts were discovered during the removal of the flowline associated with the PSC 43-11A wellhead. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced. Ensure standard operating procedures for flowline removal are followed. | maclarej | 10/25/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 705000022 | Signage at PA well (PSC 43-11) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5895741 |
| 705000023 | Location OLF removed; view SW | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5895742 |