

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2022

Submitted Date:

10/25/2022

Document Number:

702401244

FIELD INSPECTION FORM

Loc ID 318360 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241163	WELL	SI	12/01/2020	GW	123-08951	DITLEV-SIMONSEN GAS UNIT 1	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	entrance sign is adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241163 Type: WELL API Number: 123-08951 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: Ranger Energy Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): CICR 7,290 ft. Cement Volume (sx): 150

Good Return During Job: _____ Cement Type: G 15.8 lbs

Comment: Arrived on location at 1100 hrs. Swabbco workover rig was in the process of setting a CICR at 7,290 ft. circulating the wellbore to establish an injection rate. Ranger Energy Services arrived on location MIRU. Safety meeting, Pressure test lines to 4500 psi, Begin mixing and pumping 150 sxs(40.6 bbl) of 15.8 lbs. Type G cement for a squeeze. Perforations are at 7,666', 7,688', 8,116' and 8,126'.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/11/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 10-25-2022 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Due to Form 42 (MIRU) Doc # 403197610, and Form 42 (PA) Doc 403197600 Operator: Oxy/Kerr McGee Location name: Ditlev-Simonsen GU 1 API #05-123-08951 County: Weld Weather: Cloudy/Clear. Location: Dry. While there, I observed a wellsite with active PA operations at the time of inspection. During this inspection, I observed no compliance issues: See attached photos. I spoke with David Almarez/Oxy about current operations, CICR depth (7290 ft.), Cement type and volume (G/15.8 lbs. 150 sxs) and perforation depths (7666', 7688', 8116' and 8126'). No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	10/25/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401245	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5896535