

Interim Reclamation and Stormwater Inspection

October 19, 2022

Operator: VERDAD RESOURCES LLC #10651

Location ID: 425475

Inspection Document #: 697504295

Weld County, CO

SWSE Section 25 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hemberger 25-34-8-60
Location ID: 425475



Photo 1. Photo taken from the southwestern interim reclamation area, facing South. Photo illustrates unmanaged annual, weedy Kochia vegetation and bare ground with some desirable vegetation establishment. Note- introduced grass species were observed which is not reflective of reference area vegetation.



Photo 2. Photo taken from the southwestern interim reclamation area, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Hemberger 25-34-8-60
Location ID: 425475



Photo 3. Photo taken from the southwestern interim reclamation area, facing North. See comments under Photo 1.



Photo 4. Photo taken from the western interim reclamation area, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Hemberger 25-34-8-60
Location ID: 425475



Photo 5. Photo taken from the northwestern interim reclamation area, facing Northeast. See comments under Photo 1.



Photo 6. Photo taken from the northwestern interim reclamation area, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Hemberger 25-34-8-60
Location ID: 425475



Photo 7. Photo taken from the northeastern interim reclamation area, facing South. Photo illustrates what appears to be a potential topsoil stockpile lacking vegetative growth and is not stabilized.



Photo 8. Photo taken from the eastern interim reclamation area, facing South. See comments under Photo 7.

Inspection Photos
Location Name: Hemberger 25-34-8-60
Location ID: 425475




Photo 9. Reference photo taken from the western interim reclamation area, facing North. Photo illustrates desirable perennial vegetation.



Photo 10. Photo taken from the southeastern interim reclamation area. Photo illustrates an introduced grass species, Crested wheatgrass.