

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2022

Submitted Date:

10/26/2022

Document Number:

698100270**FIELD INSPECTION FORM**Loc ID 323925 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Middleton, Brett		bmiddleton@caerusoilandgas.com	<a href="#">Sr. Environmental Specialist</a>
,		COGCC.inspections@caerusoilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211241	WELL	SI	11/01/2020	GW	045-07000	KRK7 7-7 (G7E)	EI

**General Comment:**[COGCC Environmental Inspection.](#) Weather conditions during inspection were cloudy skies with a temperature of 30 degrees Fahrenheit.[Operator's Well Abandonment Report \(doc #403195524\)](#) indicates that the well has been plugged and abandoned as of September 21, 2022.[Surface equipment and wellhead had been removed prior to inspection date \(see photos\).](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Facility sign remaining at former tank battery area (see photos).

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unmarked and unused process pipe remaining in center of pad. See photos. It is recommended that the Operator mark this pipe to mitigate tripping hazard.		
Corrective Action:	Comply with Rule 606.	Date:	11/25/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 211241	Type: WELL	API Number: 045-07000	Status: SI	Insp. Status: EI

--

**Environmental****Spill/Remediation:**

Comment: [Operator's Well Abandonment Report \(doc #403195524\)](#) indicates that the well has been plugged and abandoned as of September 21, 2022. As of 10/26/2022 no Form 27 has been received from the Operator for closure of this facility.

Corrective Action: [Submit a Form 27 Site Investigation and Remediation Workplan for facility closure, per Rule 911.a.](#)

Date: 11/09/2022

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698100271	20221025 field photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5897005">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5897005</a>