

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2022

Submitted Date:

10/26/2022

Document Number:

702500687

FIELD INSPECTION FORM

 Loc ID 325560 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Overright, Issac		ioverright@maralexinc.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215004	WELL	PR	08/28/2006	GW	067-06609	HEIKKINEN 1-10	PR
443485	TANK BATTERY	AC	10/02/2015		-	Campbell Tank Battery	AC

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank sign is deteriorated (IMG 11). Produced water tank signs at tank battery are deteriorating and tank capacity is not listed (IMG 12).		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 10/30/2022
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Multiple pieces of 3" pipe near tank battery are unused (IMG 10).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.		Date: 11/10/2022
Type	WEEDS		
Comment:	Weeds at wellhead (IMG 04). Weeds at produced water tank (IMG 04 and 05). Weeds at tank battery (IMG 08 and IMG 09). Weeds at separator (IMG 07).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material, including weeds, per rule 610.k		Date: 11/03/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Wellhead and separator are enclosed by stock panel.		
Corrective Action:			Date:
Equipment:			
Type: Flow Line # 10			corrective date
Comment:	2" line from wellhead to separator, 2" line from separator to gas meter run, line to produced water tank battery, 6 4" and 3" risers with valves near gas meter run.		
Corrective Action:			Date:
Type: Gas Meter Run # 1			
Comment:	Gas meter calibration is within the last year.		
Corrective Action:			Date:
Type: Bradenhead # 1			
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Plunger Lift # 1			
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		Open Top		37.122415,-107.592740
Comment:	Open topped plastic above ground produced water tank, with mesh wildlife screen.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Weeds on tank berm are affecting permeability (IMG 05 and IMG 06).			
Corrective Action:	Remove weeds to maintain secondary containment devices per Rule 603.o.			Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4		STEEL AST		37.122731,-107.592119
Comment:	4 above ground produced water tanks.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Weeds on tank berm are affecting permeability (IMG 08 and IMG 09).			
Corrective Action:	Remove weeds to maintain secondary containment devices per Rule 603.o.			Date:

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215004 Type: WELL API Number: 067-06609 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 443485 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					
		Gravel	Pass			
		Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500688	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5897987