



Inspection Photogs
Location Name: Huntington A 1
Location ID: 325737



IMG 01
Well sign



IMG 02
Location overview




IMG 03

Culvert inlet is filled with sediment.



IMG 04

Culvert outlet is covered with sediment.



IMG 05
Erosion channel on cut slope



IMG 06
Sediment on location from erosion channel



IMG 07

Sediment on location from upgradient, near gas meter run