

Inspection Photos

API: 073-06189

Operator: MAGPIE OPERATING INC

Inspection Date: 10/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 1. Facing south toward the access road. The cattleguard has not been removed and is filled in with sediment. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 2. Facing southeast along the access road . The road has not been recontoured and culverts remain. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 3. Facing east along the access road toward the location. The road has not been recontoured and culverts remain. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos




Photo 4. Facing east at the location. The location has not been reclaimed and there is undesirable weed throughout the location. (brown veg. → Russian thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 5. There is electric utilizes and a fence in disrepair that remain at the location. All equipment should have been removed within 3 months of abandonment. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 6. Facing northeast abandoned wellsite location. There are electric utility wires that have not been removed and the location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 7. Facing northwest at the abandoned wellsite location. This area approximately 50'x50' is bare of vegetation. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 8. Drone aerial photo facing northwest toward the location. The red arrow points to the abandoned wellsite shown in photo 6-7.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos




Photo 9. Drone aerial photo facing northwest toward the location. The brown vegetation is undesirable weeds → Russian thistle. The electric utilities shown in photo 5 are located at red arrow. This area appears to be the former tank battery site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022

Inspection Photos



Photo 10. Facing toward the surrounding reference area consisting of Blue grama, Sand dropseed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06189 | Date: 10/25/2022