

Colton Limited Liability CO, Cookie Jar 1
005-07005

Inspection #688313300

10/28/2022

PA Inspection, day 2



Colorado Oil and Gas Conservation Commission
39.68936, -104.38511, 5498.7ft, 95°
10/27/2022 11:53:37 AM



ECD not used for PA

Colorado Oil and Gas Conservation Commission
39.68911, -104.38505, 5472.4ft, 248°
10/27/2022 11:54:40 AM



Colorado Oil and Gas Conservation Commission
39.68911, -104.38505, 5472.4ft, 248
10/27/2022 11:54:40 AM



Colorado Oil and Gas Conservation Commission
339.68911, -104.38505, 5472.4ft, 248°
10/27/2022 11:54:40 AM



Colorado Oil and Gas Conservation Commission
39.68896, -104.38509, 5462.6ft, 200°
10/27/2022 11:55:13 AM



Colorado Oil and Gas Conservation Commission
39.68896, -104.38509, 5462.6ft, 200'
10/27/2022 11:55:13 AM



Colorado Oil and Gas Conservation Commission

39 68897, -104 38494, 5469.2ft, 154°

10/27/2022 11:55:48 AM



Colorado Oil and Gas Conservation Commission
39.6889, -104.38469, 5465.9ft, 98
10/27/2022 11:56:17 AM



Accumulator/pipe
rams at 2000 psi

Colorado Oil and Gas Conservation Commission
39.68907, -104.38471, 5465.9ft, 342°
10/27/2022 11:56:48 AM

Greenfield
ENVIRONMENTAL SOLUTIONS

MC 1404100
VIN XHTA2051
USDOT 3851625

Colorado Oil and Gas Conservation Commission

39.6891, -104.38475, 5469.2ft, 321

10/27/2022 11:58:06 AM



Colorado Oil and Gas Conservation Commission
39.68918, -104.38492, 5479.0ft, 90°
10/27/2022 11:58:52 AM



Water in cement pump truck tanks had algae for the water zone plugs.

Colorado Oil and Gas Conservation Commission
39.68935, -104.38484, 5436.4ft, 239°
10/28/2022 04:10:41 PM

Greenfield cement
bulk truck. Not used.



Colorado Oil and Gas Conservation Commission
39.68958, -104.385, 5465.9ft, 243°
10/27/2022 12:04:46 PM