

Interim Reclamation and Stormwater Inspection

October 27, 2022

Operator: CONFLUENCE DJ LLC #10518

Location ID: 466977

Inspection Document #: 697504321

Weld County, CO

SWSW Section 22 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Willow/22 West
Location ID: 466977



Photo 1. Photo taken from the southwestern stormwater BMP area, facing East. Photo illustrates weedy, annual growth. Operator will need to reseed to achieve long-term stabilization.



Photo 2. Photo taken from the southwestern stormwater BMP area, facing South. Photo illustrates a List C Colorado noxious weed, Puncturevine.

Inspection Photos
Location Name: Willow/22 West
Location ID: 466977



Photo 3. Photo taken from the southwestern stormwater BMP area, facing West. See comments under Photos 1 and 2.



Photo 4. Photo taken from the southwestern stormwater BMP area, facing Northwest. Photo illustrates portions of the western location needing to be reclaimed.

Inspection Photos
Location Name: Willow/22 West
Location ID: 466977



Photo 5. Photo taken from the northwestern stormwater BMP area, facing South. Photo illustrates portions of the western location needing to be reclaimed and Weld County stormwater BMPs have to be revised for the interim reclamation phase.

Red arrow is pointing towards the agricultural field to the West.



Photo 6. Photo taken from the northwestern stormwater BMP area, facing East. Photo illustrates portions of the northwestern location needing to be reclaimed and Weld County stormwater BMPs have to be revised for the interim reclamation phase.

Inspection Photos
Location Name: Willow/22 West
Location ID: 466977



Photo 7. Photo taken from the northwestern stormwater BMP area, facing Northwest. Photo illustrates the end point for the diversion ditch with the agricultural field in the background.



Photo 8. Photo taken from the northwestern stormwater BMP area, facing West. Photo illustrates the agricultural field in the background.

Inspection Photos
Location Name: Willow/22 West
Location ID: 466977



Photo 9. Photo taken from the northern stormwater BMP area, facing South. Photo illustrates erosion undercutting the riprap because there is no liner.



Photo 10. Photo taken from the emergency spillway, facing West. Photo illustrates the Denver Hudson Canal.

Inspection Photos
Location Name: Willow/22 West
Location ID: 466977



Photo 11. Photo taken from the emergency spillway, facing East. Photo illustrates the retention pond. Desirable vegetation was observed along the base of the pond but weedy outside of that.



Photo 12. Photo taken west of the topsoil stockpile, facing East. Photo illustrates weedy, annual growth with some establishment of perennial grasses.

Inspection Photos
Location Name: Willow/22 West
Location ID: 466977



Photo 13. Photo taken from the western topsoil stockpile, facing East. Photo illustrates the establishment of both weedy, annuals and perennial grasses with more density of weeds.



Photo 14. Photo taken southeastern location, facing West. Photo illustrates a cut slope needing weed maintenance and stabilization.