

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2022

Submitted Date:

10/31/2022

Document Number:

700704661

FIELD INSPECTION FORM

 Loc ID 335138 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 6 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210543	WELL	PR	11/12/1995	GW	045-06299	CLOUGH 21	PR
260631	WELL	PR	12/09/2001	GW	045-07887	CLOUGH RWF 524-20	PR
286001	WELL	PR	08/02/2006	GW	045-12597	CLOUGH RMF 624-20	PR

General Comment:[COGCC Inspection Report Summary](#)

On Thursday 10/27/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Clough 21, at Location # 335138 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A from previous inspection document # 700702759 has been completed.

Approx. 15' x 75' of gravel at entrance of location.

This is a summary of inspection report.

Location

Lease Road:

Type	Access			
comment:	Approx. 15' x 75' of gravel at entrance of location.			
Corrective Action				Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD			
Comment:				
Corrective Action:				Date:

Emergency Contact Number:

Comment:	911			
Corrective Action:				Date: _____

Good Housekeeping:

Type	DEBRIS			
Comment:				
Corrective Action:				Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Plunger Lift	# 3				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 3				
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 210543 Type: WELL API Number: 045-06299 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Facility ID: 260631 Type: WELL API Number: 045-07887 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Facility ID: 286001 Type: WELL API Number: 045-12597 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704669	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5902868