

Inspection Photos

Location Name: CAERUS PICEANCE LLC BOULTON-66S92W /33SESE

Location ID: 334857



Photo #8225 From entrance to location.



Photo #8226 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BOULTON-66S92W /33SESE

Location ID: 334857



Photo #8228 Flowline insulation open ended and not capped.



Photo #8229 Flowline insulation open ended and not capped.