

Final Reclamation and Stormwater Inspection

Date: 10/24/2022

Operator: MAGPIE OPERATING INC - 52530

Location ID: 312143

Inspection Document #: 696105548

Logan County, CO

SESE Section 30 T8N R53W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 1. Taken from county road near access point, facing southwest. Photo shows presence of undesirable vegetation (e.g. kochia) and gate/fence that remains on location. The undesirable vegetation needs to be managed and the fencing/gate material needs to be properly disposed of.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 2. Taken from entrance to location, facing west. Photo show that the access road and location have not been properly decompacted with the presence of road base/gravel evident. Undesirable vegetation (e.g. kochia) was observed throughout the location and access roads.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 3. Taken near entrance to location, facing south. Photo shows pile of unidentified material (outlined in red) and crop residue/debris (left in picture) that remain on location.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 4. Taken from southern portion of well location, facing east. Photo shows non-uniform crop coverage resulting in areas of bare soil.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 5. Taken between well and location, facing east. Photo shows access road has not been reclaimed with no evidence of decompaction, gravel/road base present, and non-uniform vegetation cover.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 6. Close up photo taken from pit area. Photo shows the location was not properly decompacted.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 7. Taken from northern portion of the Pit, facing southeast. Photo shows undesirable vegetation (e.g. kochia) throughout the majority of the location.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 8. Taken from the southern portion of the pit, facing northwest. See comments in photo 7.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 9. Taken from the southern portion of the pit, facing north. See comments in photo 7.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 10. Taken from the northern portion of the pit, facing south. See comments in photo 7.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 11. Taken from the southeastern portion of the location, facing north. Photo shows fence installed along east side of location. This is considered debris and needs to be removed.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 12. Close up photo taken of unidentified material (background, red outline) and crop residue/debris pile that remain on location.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 13. Reference area photo taken from the southwestern corner of location, facing west.

Inspection Photos

Location Name: WARNECKE- 68N53W 30 SESE

Location ID: 312143



Photo 14. Google Earth aerial imagery illustrates area (outlined in red) that needs to be reclaimed ASAP. Refer to inspection report for additional details.