

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2022

Submitted Date:

11/03/2022

Document Number:

696204286**FIELD INSPECTION FORM**

Loc ID 412922	Inspector Name: Trujillo, Aaron	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 7 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10515</u> Name of Operator: <u>GUNNISON ENERGY LLC</u> Address: <u>1801 BROADWAY #1150</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
		geops@oxbow.com	
		Tyson.Johnston@oxbow.com	
		Heather.Lang@oxbow.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412922	LOCATION	AC			-	DGU Federal 1289 17-11 Pad	RI
436561	WELL	AL	11/01/2018	LO	051-06123	DGU Federal 1289 17-11 CS2	AL

**General Comment:**

On 11/1/2022, Reclamation Specialist Trujillo, and Reclamation Supervisor Arthur inspected Gunnison Energy's DGU Federal 1289 17-11 pad location in Gunnison County, Colorado.

This inspection is a followup to #696202043 and #696203553 to document compliance with the following corrective actions:

- §34-60-121(1)(a), C.R.S.: Form 4 condition requirements- Signage
- Plugging and abandonment of conductor.

It was observed that this Location remains out of compliance with COGCC Rules and corrective actions

The following new compliance issues were observed per this inspection:

- Location Signage
- Protection of stockpiled soils.
- Anchors improperly marked.

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	<p>Pursuant to conditions within the 502.b Delayed Interim Reclamation NTO document #401463219, Operator was required to post a sign at the location entrance stating the following: "A COGCC variance has been approved to delay the commencement of interim reclamation to no later than December 9, 2022".</p> <p>It was observed that a sign has been placed at the Location entrance, however sign has not been properly secured and is now considered debris. Sign is also made of poor quality material and is showing sign of deterioration.</p>		
Corrective Action:	Maintain Delayed Interim Reclamation NTO signage.	Date:	11/10/2022
Type	OTHER		
Comment:	It was observed in this inspection that the Location signage at the entrance of the Location has been removed.		
Corrective Action:	Install Location signage.	Date:	12/01/2022

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>412922</u>	Type:	<u>LOCATION</u>	API Number: <u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>	
Facility ID:	<u>436561</u>	Type:	<u>WELL</u>	API Number:	<u>051-06123</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Fail \_\_\_\_\_

Comment \_\_\_\_\_

Soil stockpiles observed on the north end of the Location. BMPs to protect stockpiles from wind and water erosion, as well as to minimize erosion, degradation and sediment transport are missing or insufficient.

Corrective Action \_\_\_\_\_

Comply with Rule 1002.c and 1002.f.

Date **11/10/2022**

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Markers at anchors have not been maintained in a proper condition.

Corrective Action \_\_\_\_\_

Maintain markers.

Date **11/18/2022**

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment Operator received a 502.b Delayed Interim Reclamation variance. See Sundry #401463219 for additional details; variance expires 12/9/2022; interim reclamation work on the Location is required to be completed by 12/9/2022. A followup inspection will be conducted to document compliance with 1003 rules and Sundry Conditions of Approval.

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Previous inspections observed that the conductor for the abandoned well API #05-051-06123 has not been plugged and reclaimed per Rule 406 Requirements. Inspection required Operator to comply with Rule 406.e.(4).

It was observed in this inspection that the conducted and related cellar have been removed, however no Form 4 "Report of Work Done, Other: Plugged Conductor for the Oil and Gas Location" to report the plugging of the conductor has been submitted. Corective action has not been addressed and remains applicable.

Corrective Action: **Comply with Rule 406.e.(4)**

Date **05/31/2022**

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204287	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905367">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905367</a>