

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2022

Submitted Date:

11/03/2022

Document Number:

702500722

FIELD INSPECTION FORM

Loc ID 334302 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260466	WELL	PR	11/01/2020	CBM	067-08494	HESTER 2	PR
295866	WELL	PR	05/05/2008	CBM	067-09553	HESTER 4	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank capacity is not labeled (IMG 04).		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 01/03/2023
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Metal stairs are not in use (IMG 07). 4 pieces of metal pipe are not in use near #2 gas meter run (IMG 06).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.		Date: 11/11/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Equipment on this location is enclosed by stock panel.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run			# 2
Comment:			#4 gas meter calibration is within the last year. #2 last reported gas meter calibration: 12.22.20 (IMG 05).
Corrective Action:			Confirm annual calibration has been completed or perform annual calibration per rule 430.d.(1). Date: 12/03/2022
Type: Bird Protectors			# 2
Comment:			Separator vent stacks are screened.
Corrective Action:			Date:
Type: Bradenhead			# 2
Comment:			Bradenheads are accessible.
Corrective Action:			Date:
Type: Vertical Heated Separator			# 1
Comment:			
Corrective Action:			Date:
Type: Prime Mover			# 2
Comment:			Electric

Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	2 telemetry, 2 pump control panels, electric cabinet		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 9		
Comment:	3" and 1" lines from #4 wellhead to separators, 2" line from separator to produced water, 4" line from gas meter run to flow line riser, 3" line from #2 wellhead to separator, 2" line from separator to produced water tank, 4" line from gas meter run to flow line riser. 2 4" produced water flow line risers.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV STEEL		37.212932,-107.790343
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	21 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.212659,-107.789759
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity) 95 bbl	
Other (Type) cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No					
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 260466 Type: WELL API Number: 067-08494 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 295866 Type: WELL API Number: 067-09553 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Gravel	Pass			
Gravel	Pass					
		Compaction	Pass			

Comment: Small channel beginning to form at location entrance (IMG 03).

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500723	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905380