

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUNN-67S92W /9NWNE

Location ID: 334833



Photo #8266 From entrance to location.



Photo #8267 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUNN-67S92W /9NWNE

Location ID: 334833



Photo #8268 From entrance to location.



Photo #8269 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUNN-67S92W /9NWNE

Location ID: 334833



Photo #8270 Location lacks stabilization.



Photo #8271 BMP's have not been implemented around stockpiled soils.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUNN-67S92W /9NWNE

Location ID: 334833



Photo #8272 Insufficient tracking BMP at entrance to location.