

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401767353

Date Received:

09/19/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Amato, Joseph

719-845-2110/719-859-2263

josephamato@tcenergy.us

Santistevan, Vince

719-845-2102/719-680-9705

vincesantistevan@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 687903055

Inspection Date: 08/22/2018

FIR Submit Date: 08/23/2018

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308378

Location Name: APACHE CANYON-634S68W Number: 1SENE County: LAS ANIMAS

Qtrqtr: SENE Sec: 1 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.109310 Longitude: -104.950530

FACILITY - API Number: 05-071- -00 Facility ID: 270571

Facility Name: APACHE CANYON Number: 1-14

Qtrqtr: SENE Sec: 1 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.109310 Longitude: -104.950530

CORRECTIVE ACTIONS:

1 ☒ CA# 118144

Corrective Action: Need to replace broken corrugated pipe.

Date: 09/23/2018

Response: CA COMPLETED

Date of Completion: 09/18/2018

Operator Comment: The damaged galvanized culvert on the main lease road was replaced with a new galvanized culvert. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC Representative:			
-----------------------	--	--	--

2	<input checked="" type="checkbox"/>	CA# 118145	
Corrective Action:		Need to address erosion and rutting on access lease road.	Date: 09/23/2018
Response:		CA COMPLETED	Date of Completion: 09/18/2018
Operator Comment:		The access lease road was crowned to create sheet flow which eliminated the tire rutting and surface erosion. See attached photo log for details.	
COGCC Decision:		Approved pending re-inspection	
COGCC Representative:			

3	<input checked="" type="checkbox"/>	CA# 118146	
Corrective Action:		Address erosion, rutting and replace broken corrugated pipe.	Date: 09/23/2018
Response:		CA COMPLETED	Date of Completion: 09/18/2018
Operator Comment:		The access lease road was crowned to create sheet flow which eliminated the tire rutting and surface erosion. The damaged galvanized culvert on the main lease road was replaced with a new galvanized culvert. See attached photo log for details.	
COGCC Decision:		Approved pending re-inspection	
COGCC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	The surface erosion and tire rutting on the access lease road have been addressed. The damaged culvert on the main lease road was replaced with a new culvert.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Edie Fitzgerald	Signed: _____
Title: Sr. Environmental Tech.	Date: 9/19/2018 7:30:46 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401767353	FIR RESOLUTION SUBMITTED
401767359	Culvert replacement and erosion/tire rut repairs

Total Attach: 2 Files