

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2022

Submitted Date:

11/04/2022

Document Number:

707600490

**FIELD INSPECTION FORM**

Loc ID 306584 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289855	WELL	PR	06/01/2021	OW	123-24950	SHOEMAKER A 12-8	PR

**General Comment:**

This is a WELL / BATTERY inspection.  
 Well(s): 1: Producing | PR.  
 Battery: Active.

Centralized Battery serves 4 Location IDs  
 (306584, 306585, 306586, 306587).  
 (Well(s): 3: Producing | PR ; 1: Temporarily Abandoned | TA).

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: <input style="width: 100px;" type="text"/>

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Gas Meter Run	# 1			
Comment:	Gas Sales: Calibration card indicates calibration within last year. Last calibration: 05/13/2022. Active, w/ production.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	ECD scrubbers.			
Corrective Action:				Date:
Type: Emission Control Device	# 2			
Comment:	ECD 1: Crude storage vapor line combustor(s). Controls crude oil tanks vapors. Pilots: ON.  ECD 2: Separator vapor line combustor(s). Controls crude oil tanks vapors. Pilots: ON.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 4 Location IDs (306584, 306585, 306586, 306587). (Well(s): 3: Producing   PR ; 1: Temporarily Abandoned   TA).				
Corrective Action:					Date:

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)	53 Bbls.					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: <a href="#">Shares berms w/ crude oil tank(s).</a>						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		40.501549,-104.491986	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: <a href="#">Shares berms w/ produced H2O vault(s).</a>						
Corrective Action:					Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:					Date:

Flaring:

Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 289855 Type: WELL API Number: 123-24950 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 08/30/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 11/02/2022 at approximately 15:46 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: SHOEMAKER A-66N64W/12SENE  Location ID: 306584  Well Name(s):  Shoemaker A 12-8.  API:  123-24950.  Location County: Weld County, Colorado  Weather: Mostly Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Producing   PR.  Battery: Active.</p> <p>Centralized Battery serves 4 Location IDs (306584, 306585, 306586, 306587).  (Well(s): 3: Producing   PR ; 1: Temporarily Abandoned   TA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/04/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600491	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5906309">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5906309</a>