

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/07/2022

Document Number:

702500741**FIELD INSPECTION FORM**Loc ID 312126 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214662	WELL	PR	01/01/2022	CBM	067-06266	TIFFANY EAST 2-17	PR
299610	WELL	PR	02/10/2010	CBM	067-09647	TIFFANY EAST 3-17	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank has no tank sign/placard (IMG 06 and IMG 07).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/07/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Trough, 2" pipe. and pipe attachment at 2-17 wellhead are not in use. Unused wire fencing at produced water tank (IMG 04).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.	Date:	11/15/2022
Type	WEEDS		
Comment:	Weeds at produced water tank (IMG 05).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k	Date:	11/15/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	OTHER		
Comment:	Equipment at this location is enclosed by steel fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Telemetry, 2 pump control panels, electric panel, valve cluster pit		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	Separator and tank vent are screened.		
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 10		
Comment:	3" and 2" lines from 3-17 wellhead to separator, 3" and 2" lines from 2-17 wellhead to separator, 1" line from separator to produced water tank transfer pump, 2 3" lines from gas meter run to supplemental gas meter run, 2 2" lines from separators to produced water tank. 4" line to pig station.		
Corrective Action:			Date:
Type: Other	#		
Comment:	Produced water transfer pump at tank. Chemical container with spill prevention.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		STEEL AST		37.021594,-107.526810
Comment:	Above ground produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)	Cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 214662 Type: WELL API Number: 067-06266 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 299610 Type: WELL API Number: 067-09647 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			
		Gravel	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500742	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5907541