

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/07/2022

Document Number:

702500743**FIELD INSPECTION FORM**Loc ID 333116 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213801	WELL	PR	02/01/2022	CBM	067-05064	ABEYTA 17-1	PR
295624	WELL	PR	09/13/2008	CBM	067-09535	ABEYTA 17-2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Lube oil at prime mover has stained concrete (IMG 03).		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused valve at separator (IMG 05). Unused 1/2" tubing at gas meter run (IMG 07). Unused 2" pipe at separator (IMG 06). Unused reflective wrap and pipe fitting at prime mover (IMG 04).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.	Date:	11/15/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Equipment on this location enclosed by wire and metal fencing.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 2		
Comment:	Telemetry, valve cluster pit,		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered.		
Corrective Action:		Date:	

Type: Bird Protectors	# 2		
Comment:	Separator vent stacks are screened properly.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 8		
Comment:	2 2" lines from each wellhead to separator, 1" line from separator to gas powered prime mover, 2" line near sound panel at pump jack, 2 2" lines from separators to produced water off location,		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 213801 Type: WELL API Number: 067-05064 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/03/2022Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 295624 Type: WELL API Number: 067-09535 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500744	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5907542