

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/07/2022

Document Number:

702500737

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 325235 _____ Klink, Alex _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10679
 Name of Operator: LOGOS OPERATING LLC
 Address: 2010 AFTON PLACE
 City: FARMINGTON State: NM Zip: 87401

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, General		regulatory@logosresourcesllc.com	All SW field inspections
Fields, Vanessa		vfields@logosresourcesllc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214370	WELL	TA	07/01/2020	GW	067-05781	ESPINOSA 1	TA

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Produced water tank is enclosed by wire fencing.

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date: _____
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date: _____
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date: _____
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened.		
Corrective Action:			Date: _____
Type: Gas Meter Run	# 1		
Comment:	Last reported gas meter calibration: 6.23.08, (IMG 03). Meter must be calibrated if well is returned to service.		
Corrective Action:			Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.015978,-107.510726
Comment:	Open topped produced water tank is upside down and not in use (IMG 05).				
Corrective Action:					Date: _____

Paint

Condition Adequate

Other (Content)	
Other (Capacity) 20 bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Berm height is diminished (IMG 05). If well is returned to service, berms must be repaired/maintained.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214370 Type: WELL API Number: 067-05781 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Compaction	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500738	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5907539