

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/08/2022

Document Number:

702500735

FIELD INSPECTION FORM

 Loc ID 334042 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 74650Name of Operator: RIM OPERATING INCAddress: 5 INVERNESS DRIVE EASTCity: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Rector, Libby	720-221-1675	Lrector@rimop.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	
Rector, Mike	720-221-1677	mhr@rimop.com	SW Inspection Reports
Ortiz, Liz	303-799-9828 Ext. 304	lortiz@rimop.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289620	WELL	SI	10/01/2019	GW	067-09333	PAYNE C-2	PR
289621	WELL	PR	03/01/2012	CBM	067-09332	PAYNE C 1A	PR
299999	WELL	PR	06/22/2010	CBM	067-09651	PAYNE 22	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type TANK BATTERY

Comment: [Produced water tanks enclosed by wire fencing.](#)

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Bird Protectors	# 7			
Comment:	Tanks and separator vent stacks are screened.			
Corrective Action:				Date: _____
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:				Date: _____
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date: _____
Type: Ancillary equipment	# 2			
Comment:	Telemetry, cathodic protection			
Corrective Action:				Date: _____
Type: Flow Line	# 13			
Comment:	3" and 2" line from each wellhead to separators, 3 2" lines from separators to produced water tanks, 4 1" lines at separators.			
Corrective Action:				Date: _____
Type: Gas Meter Run	# 3			
Comment:	Gas meter calibrations are within the last year.			
Corrective Action:				Date: _____
Type: Bradenhead	# 3			
Comment:	Bradenheads are accessible.			
Corrective Action:				Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	<100 BBLs	Open Top		37.013382,-107.521530
Comment: Partially buried open topped produced water tank with steel mesh screen covering.					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity) 95 bbl					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		37.013373,-107.522018
Comment: Partially buried open topped produced water tank with steel mesh screen covering.					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity) 95 bbl					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	STEEL AST		37.013349,-107.521726
Comment: 4 above ground produced water tanks, each with 300 bbl capacity.					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity) 300 bbl each					
Other (Type) cone top					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					Date:

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 289620 Type: WELL API Number: 067-09333 Status: SI Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 289621 Type: WELL API Number: 067-09332 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 299999 Type: WELL API Number: 067-09651 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
		Compaction	Pass			
Compaction	Pass					
Waddles	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500736	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5907772