

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/08/2022

Document Number:

700901269**FIELD INSPECTION FORM**Loc ID 320297 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10675Name of Operator: DANMAR PRODUCTION COMPANY LLCAddress: 3945 18TH STREET LANECity: GREELEY State: CO Zip: 80634**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dbaker57@comcast.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203389	WELL	TA	01/01/2021	OW	001-08898	CIMYOTTE 6-21	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Rule 606: Weeds, dead weeds.		
Corrective Action:	With in the designated setback, remove debris and weeds per Rule 606. Corrective Action Date 12/2/2022. See attached photo # 1 through 4	Date:	12/02/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Shares berm with crude</a>					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.913173,-104.595198
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment: <a href="#">Rule 906. Stained soil around load out bucket.</a>					
Corrective Action: <a href="#">Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/9/2022 to remove stained soil. See attached photo # 3.</a>					Date: <a href="#">12/09/2022</a>

**Wells Served By Facilities Above**

API Number	
001-08898	

**AirsID**

API Number	AirsID

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 203389 Type: WELL API Number: 001-08898 Status: TA Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 01/16/2022 Annual Brhd Completed? \_\_\_\_\_Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: unable to see bradenhead due to weeds

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday, November 7th, 2022 at approximately 11:00am. I, Inspector Chane Finkenbinder, conducted an on-site inspection.</p> <p>Operator: DANMAR P.C. LLC</p> <p>Location name: Cimyotte 6-21</p> <p>API # 001-08898</p> <p>Location ID #: 320297</p> <p>County: Adams</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ul style="list-style-type: none"> <li>• Rule 606: Weeds, dead weeds. With in the designated setback, remove debris and weeds per Rule 606. Corrective Action Date 12/2/2022. See attached photo # 1 through 4.</li> <li>• Rule 906. Stained soil around load out bucket. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/9/2022 to remove stained soil. See attached photo # 3.</li> </ul> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	11/08/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700901270	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908095</a>