

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/07/2022

Document Number:

699805175

FIELD INSPECTION FORM

 Loc ID 324021 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211512	WELL	PR	05/20/1998	GW	045-07272	UNOCAL GM 12-1	PR

General Comment:

[COGCC Inspection Report Summary](#)
 On Monday 11/7/22 at approximately 10:30 hours, I, Inspector Corey De Paolo,
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1SWNW.
 Location #324021 in Garfield County Colorado.
 While there, I observed normal production operations.
 This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	No tank battery located on location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Gas Meter Run		# 1		
Comment:				
Corrective Action:			Date:	
Plunger Lift		# 1		
Comment:	Well on plunger lift			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 211512 Type: WELL API Number: 045-07272 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
		Check Dams				
		Culverts				
Gravel						
		Berms				
Ditches						
Berms						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for comments	depaoloc	11/07/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805176	Photos for Insp. #699805175	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908088