

Inspected Facilities

Facility ID: 483137 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment	Operator is conducting a dig and haul operation. Some material remains stockpiled with a temporary berm.			
Corrective Action				Date:

Spill/Remediation:

Comment:	<p>COGCC Inspection of spill on the MSSU19-5 injection flowline. COGCC Staff met Operator personnel and Larimer County personnel onsite.</p> <p>Operator has exposed the flowline at the failure point and scraped surface impacts into a stockpile to be removed for disposal. No standing liquid was observed. Operator indicates flowline has been shut-in and depressurized. Operator will continue removal of impacted soil and perform confirmation soil sampling. Operator will notify COGCC of confirmation soil sampling schedule to allow for COGCC split sampling. Form 19 Supplemental is due 11/4/2022.</p>		
Corrective Action:			Date: _____

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693701029	Removed flowline with corrosion hole	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908285
693701030	Excavation of flowlines at failure point	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908286
693701031	Temporary soil stockpile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908287
693701032	East end of surface impacts looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5908288