

Prospect Energy - COGCC Inspection Photos
MSSU 19-5 Injection Well Flowline
Spill ID #483137 Date 11/02/2022



Flowlines exposed in excavation; repair completed on produced water injection flowline. View east toward MSSU 19-5 injection well. Located at approx 40.648722, -105.049226



View of flowlines exposed in excavation at release point. (1) 2" carbon steel flowline repaired; approximately 15' of 2" CS FBE coated pipe welded into place (welds to be coated) in area of failure. (1) poly natural gas flowline running tandem in same trench.

Prospect Energy - COGCC Inspection Photos
MSSU 19-5 Injection Well Flowline
Spill ID #483137 Date 11/02/2022



Corrosion hole identified on flowline pipe; MSSU 19-5 PW Injection flowline (off location). Coating damage observed in area of failure.



Internal photo of failed section of MSSU 19-5 flowline pipe.

Prospect Energy - COGCC Inspection Photos
MSSU 19-5 Injection Well Flowline
Spill ID #483137 Date 11/02/2022



Isolation valve installed on MSSU 19-5 flowline adjacent to/ west of Krauss Battery. Valve can to be installed for access.



Flowline pressure test witnessed; crystal gauge reading near end of pressure test (verification of repairs completed).