

# Final Reclamation and Stormwater Inspection

Date: 11/02/2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 320397

Inspection Document #: 696105572

Adams County, CO

NENE Section 1 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 1.** Google Earth aerial imagery taken circa 2006 illustrates the access road and location that need to be reclaimed.

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 2.** Taken near the entrance of the access road, facing west. Photo shows tank battery location is predominantly undesirable vegetation (e.g. kochia) and access road has not been reclaimed.

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 3.** Taken from southern portion of tank battery location, facing northeast. Photo illustrates vehicle tracks through the disturbance area.

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 4.** Taken from the well location, facing southeast. Photo illustrates the location appears to have been revegetated. A follow-up inspection will need to be performed at a later date to verify revegetation.

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 5.** Taken from the southern portion of the location, facing northeast. See comments in Photo 4.

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 6.** Taken from the eastern portion of the location, facing northwest. See comments in Photo 4.

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 7.** Photo taken from across the access road, north of the reclaimed location, facing northeast. Photo illustrates reference area appears to have been revegetated.

Inspection Photos  
Location Name: HSR EPPINGER #1-1  
Location ID: 320397



**Photo 8.** Taken from the location, facing north. Photo illustrates water supply equipment located north of the location. It appears the access road is being used by the water district; the access road will need to be reclaimed in order to reach final reclamation standards.