


**APPENDIX A**

**SITE PHOTOS**



**Description:**

#1 - Phelps 11-32CHZ AST Release Site



**Description:**

#2 - A Pinhole Failure in the AST Shell Caused the Release

**Photo Log**



**Description:**

#3 - Looking North at AST that Failed. Note Synthetic Liner Beneath ASTs.


**Photo Log**



**Description:**

#4 - Looking West at AST that Failed. Impacted Soil has been removed above the liner and partially beneath the AST.

**Photo Log**



**Description:**

#5 - Looking West at Impacted Area. Pink Line Represents Further Excavation Required.

**Photo Log**



**Description:**

#6 - Looking North at Impacted Area. Note Standing Water Above Liner Indicating Liner Integrity

## Photo Log



**Description:**

#7 - Looking West While AST is Removed from the Tank Battery

## Photo Log



**Description:**

#8 - Inspection of the Bottom of the AST; No Failures Observed in Tank Floor.

**Photo Log**



**Description:**

#9 - Looking South at Former AST Pad During Sampling

**Photo Log**



**Description:**

#10 - Looking West at Former Tank Pad. Pink Line Indicates Area Requiring Further Excavation.