

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER-66S92W /32NESW

Location ID: 334837



Photo #8330 From entrance to location.



Photo #8331 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER-66S92W /32NESW

Location ID: 334837



Photo #8332 From entrance to location.



Photo #8333 Chemical tank missing required information.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER-66S92W /32NESW

Location ID: 334837



Photo #8334 Location lacks stabilization.



Photo #8335 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER-66S92W /32NESW

Location ID: 334837



Photo #8336 Location lacks stabilization.



Photo #8337 Insufficient tracking BMP at entrance.