

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2022

Submitted Date:

11/09/2022

Document Number:

702500759**FIELD INSPECTION FORM**Loc ID 326297 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216188	WELL	PR	03/16/1993	CBM	067-07794	HUBER-LEWIS 2-33	PR
455098	GAS COMPRESSOR STATION	AC	05/23/2018		-	HUBER-LEWIS 02-33 FC - CDP	AC

General Comment:

Inspector Alex Klink on site to conduct follow up inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	An additional label was added to tank hatch (IMG 04), however tank capacity is not legible. CA from previous inspection Doc# 702500327 has not been satisfactorily completed. CA date from previous inspection remains.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/06/2022

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Impacted material at compressor skid (IMG 05 and IMG 06). Impacted material at pump jack (IMG 07 and IMG 08).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	11/17/2022
Type	UNUSED EQUIPMENT		
Comment:	CA from previous inspection Doc# 702500327 has been satisfactorily completed.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lube oil at compressor skid has nearly filled spill prevention (IMG 05). Lube oil at pump jack has stained concrete and has impacted surface material (IMG 07 and IMG 08).		
Corrective Action:	Remove oil and oily residue and dispose of in approved manner per rule 906 and 1002.f.	Date:	11/11/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216188 Type: WELL API Number: 067-07794 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 455098 Type: GAS API Number: - Status: AC Insp. Status: AC

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500760	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5910783