

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2022

Submitted Date:

11/09/2022

Document Number:

700704694**FIELD INSPECTION FORM**Loc ID 335195 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281732	WELL	PR	02/01/2021	GW	045-11508	JONSSON 19-02D	PR
281734	WELL	PR	02/01/2021	GW	045-11511	JONSSON 19-07B	PR
281740	WELL	PR	02/01/2021	GW	045-11517	JONSSON 19-07C	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 11/7/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Jonson 19-08, at Location # 335195 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A's (Lack of stabilization and cut slope erosion and lack of stabilization) from previous inspection document # 700704090 has not been completed. Therefore C/A date remains the same.

During this inspection the following compliance issues were observed:

1. Location and cut slope shows some signs of lack of stabilization from previous inspection has not been completed (C/A date remains 6/3/2022)

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
	Type Access			
	comment:			
	Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type OTHER			
	Comment: Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
	Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS			
	Comment:			
	Corrective Action:		Date:	
	Type BATTERY			
	Comment:			
	Corrective Action:		Date:	
	Type WELLHEAD			
	Comment:			
	Corrective Action:		Date:	
Emergency Contact Number:				
	Comment: 911			
	Corrective Action:		Date:	
<b>Good Housekeeping:</b>				
	Type DEBRIS			
	Comment:			
	Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment:			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
				corrective date
Type: Horizontal Heated Separator	# 4			
	Comment:			
	Corrective Action:		Date:	
Type: Emission Control Device	# 1			
	Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 281732 Type: WELL API Number: 045-11508 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 281734 Type: WELL API Number: 045-11511 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 281740 Type: WELL API Number: 045-11517 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: 1. Location and cut slope shows some signs of lack of stabilization from previous inspection has not been completed (C/A date remains 6/3/2022)

Corrective Action: Install or repair required BMPs

Date: 06/03/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704698	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5910856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5910856</a>