

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2022

Submitted Date:

11/03/2022

Document Number:

702500722**FIELD INSPECTION FORM**Loc ID 334302 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email                         | Comment                  |
|------------------|-------|-------------------------------|--------------------------|
| Labowskie, Steve |       | steve.labowskie@state.co.us   |                          |
| , General        |       | sjninspections@ikavenergy.com | All SW field inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 260466      | WELL | PR     | 11/01/2020  | CBM        | 067-08494 | HESTER 2      | PR          |
| 295866      | WELL | PR     | 05/05/2008  | CBM        | 067-09553 | HESTER 4      | PR          |

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TANK LABELS/PLACARDS                                  |       |            |
| Comment:           | Produced water tank capacity is not labeled (IMG 04). |       |            |
| Corrective Action: | Install sign to comply with Rule 605.h.               | Date: | 01/03/2023 |

**Emergency Contact Number:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  | Date: |  |

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | UNUSED EQUIPMENT  |       |            |
| Comment:           | Metal stairs are not in use (IMG 07). 4 pieces of metal pipe are not in use near #2 gas meter run (IMG 06). |       |            |
| Corrective Action: | All unused equipment must be returned to use or stored off location per rule 606.                           | Date: | 11/11/2022 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | OTHER  |       |  |
| Comment:           | Equipment on this location is enclosed by stock panel. |       |  |
| Corrective Action: |  | Date: |  |

**Equipment:**

|                                   |  |       |                 |
|-----------------------------------|--|-------|-----------------|
| Type: Ancillary equipment         | # 5  |       | corrective date |
| Comment:                          | 2 telemetry, 2 pump control panels, electric cabinet |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Horizontal Heated Separator | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Progressive Cavity          | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Pump Jack                   | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Flow Line                   | # 9  |       |                 |

|                                 |   |  |  |       |            |
|---------------------------------|---|--|--|-------|------------|
| Comment:                        | 3" and 1" lines from #4 wellhead to separators, 2" line from separator to produced water, 4" line from gas meter run to flow line riser, 3" line from #2 wellhead to separator, 2" line from separator to produced water tank, 4" line from gas meter run to flow line riser. 2 4" produced water flow line risers. |  |  | Date: |            |
| Corrective Action:              |   |  |  | Date: |            |
| Type: Prime Mover               | # 2   |  |  |       |            |
| Comment:                        | Electric  |  |  | Date: |            |
| Corrective Action:              |   |  |  | Date: |            |
| Type: Bird Protectors           | # 2   |  |  |       |            |
| Comment:                        | Separator vent stacks are screened.   |  |  | Date: |            |
| Corrective Action:              |   |  |  | Date: |            |
| Type: Gas Meter Run             | # 2   |  |  |       |            |
| Comment:                        | #4 gas meter calibration is within the last year.<br>#2 last reported gas meter calibration: 12.22.20 (IMG 05).   |  |  | Date: |            |
| Corrective Action:              | Confirm annual calibration has been completed or perform annual calibration per rule 430.d.(1).   |  |  | Date: | 12/03/2022 |
| Type: Bradenhead                | # 2   |  |  |       |            |
| Comment:                        | Bradenheads are accessible.   |  |  | Date: |            |
| Corrective Action:              |   |  |  | Date: |            |
| Type: Vertical Heated Separator | # 1   |  |  |       |            |
| Comment:                        |   |  |  | Date: |            |
| Corrective Action:              |   |  |  | Date: |            |

**Tanks and Berms:**

| Contents           | #                                     | Capacity  | Type      | Tank ID | SE GPS                |
|--------------------|---------------------------------------|-----------|-----------|---------|-----------------------|
| PRODUCED WATER     | 1                                     | <100 BBLs | PBV STEEL |         | 37.212659,-107.789759 |
| Comment:           | Partially buried produced water tank. |           |           |         |                       |
| Corrective Action: |                                       |           |           |         | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 95 bbl   |
| Other (Type)     | cone top |

**Berms**

| Type               | Capacity                              | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
|--------------------|---------------------------------------|---------------------|---------------------|-------------|-----------------------|
| Metal              | Adequate                              | Walls Sufficient    | Base Sufficient     | Adequate    |                       |
| Comment:           |                                       |                     |                     |             |                       |
| Corrective Action: |                                       |                     |                     | Date:       |                       |
| Contents           | #                                     | Capacity            | Type                | Tank ID     | SE GPS                |
| PRODUCED WATER     | 1                                     | <50 BBLs            | PBV STEEL           |             | 37.212932,-107.790343 |
| Comment:           | Partially buried produced water tank. |                     |                     |             |                       |
| Corrective Action: |                                       |                     |                     |             | Date:                 |

**Paint**

Inspector Name: Klink, Alex

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 21 bbl   |  |
| Other (Type)     | cone top |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 260466 Type: WELL API Number: 067-08494 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 295866 Type: WELL API Number: 067-09553 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |

Comment: [Small channel beginning to form at location entrance \(IMG 03\).](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403219005    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905385">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905385</a> |
| 702500723    | Photo doc            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905380">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5905380</a> |