

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2022

Submitted Date:

11/10/2022

Document Number:

688313344

### FIELD INSPECTION FORM

Loc ID 433299 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Civitas		Inspections@civiresources.com	
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433755	WELL	SI	01/01/2022	OW	005-07212	Cline 4-64 2 1H	TA

**General Comment:**

[Routine Field Inspection](#)

[LO/TO needed on produced water tank and gas sales risers.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Maintain NFPA labels (see attached photos).		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-659-7740

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Flare	# 1		
Comment:	not on		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	horse head and bridle are off		
Corrective Action:		Date:	
Type: FWKO	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		

Comment: <a href="#">Abandone</a> s/risers on gas sales line need to be LO/TO.			
Corrective Action:	<a href="#">Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.</a> or <a href="#">Maintain active and inactive flowlines and crude oil transfer lines to meet rule 1102.i.</a>	Date:	<a href="#">11/11/2022</a>
Type: Bradenhead	# 1		
Comment: <a href="#">No gauge on bradenhead.</a>			
Corrective Action:	<a href="#">Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).</a>	Date:	<a href="#">11/25/2022</a>
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment: <a href="#">metal berms</a>			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: <a href="#">electric motor</a>			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 0		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment: <a href="#">not on</a>			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment: <a href="#">not connected, no LO/TO</a>					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	same metal berms as crude oil tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
<b>Wells Served By Facilities Above</b>					
API Number		<b>AirsID</b>			
005-07212		API Number		AirsID	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 433755 Type: WELL API Number: 005-07212 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 1/1/2022. Well is TA because pumping unit requires maintenance to turn it on.

Document #402981862 Form 04 (OBJ-OTHER) -00 Other: Production Test Attachment  
count: 2 APPROVED 4/6/2022 3/10/2022 CRESTONE PEAK RESOURCES  
OPERATING LLC

Last MIRU:  
Document #402931315 Form 42 (MIRU) -00 Notice Type: MIRU  
Date&Time: 01/21/2022 06:00 APPROVED 1/19/2022 1/19/2022 CRESTONE PEAK  
RESOURCES OPERATING LLC

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688313361	Crestone Cline 4-64 2 1H	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5912161">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5912161</a>