

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/11/2022

Submitted Date:

11/11/2022

Document Number:

705000040

**FIELD INSPECTION FORM**

Loc ID 320352 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1775 SHERMAN STREET STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
320352	LOCATION	CL			-	WIERMAN-61S67W 7NESE	EG

**General Comment:**

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photo uploaded](#)

**Inspected Facilities**

Facility ID: 320352 Type: LOCATION API Number: - Status: CL Insp. Status: EG

**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: COGCC Inspector spoke with PDC Energy personnel on location. Well (Wierman 43-7-1) has been plugged and abandoned; cut and cap operations are completed (2019). The wellhead flowline, dump and process flowlines (OL) have been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. No flowline risers observed at the (PA) wellhead or facility/ battery areas. A fenced excavation was observed; remediation work to remove impacted soils (historical) is in progress.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403226260 received on 11/10/2022: During reclamation activities, an historic release was discovered at the former Wierman 43-7-1 tank battery.	maclarej	11/11/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000041	Excavation work on location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913116">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913116</a>
705000042	Location view west; No flowline risers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913117">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913117</a>