


Inspection Photos
Location Name: Champlin 248 AmocoC#5
Location ID:320092



Photo#1 Pumpjack/Wellhead